

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave.St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:**Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-008130**Date Inspected:** 31-Jul-2009**Project Name:** SAS Superstructure**OSM Arrival Time:** 1900**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 700**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Guo Peng**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** Tower&OBG**Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance (QA) Inspector, Utekar Shrikant was present during the times noted above for observations relative to the work being performed.

BAY#10

This QA Inspector randomly observed the following work in progress

SAW welding process of weld joint 4B located on PCMK ND1-A6002-11. Welder is identified as 040489 ZPMC QC is identified as Dang Zhi Bing. The welding variables recorded by QC appeared to comply with the WPS-B-T-4221-B-U3C-S-1.

BAY#11

This QA Inspector randomly observed the following work in progress.

FCAW welding process of weld joint 5 located on PCMK WSD1-FESA4-2B/C. Welders are identified as 066484 ZPMC QC is identified as Lin Li. The welding variables recorded by QC appeared to comply with the WPS-B-T-2332-TC-P5-F.

FCAW welding process of weld joint 6 located on PCMK WSD1-FESA4-2B/C. Welders are identified as 066683 ZPMC QC is identified as Lin Li. The welding variables recorded by QC appeared to comply with the

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

WPS-B-T-2332-TC-P5-F.

FCAW welding process of weld joint 5 located on PCMK WSD1-FESA4-2C/C. Welders are identified as 066882 ZPMC QC is identified as Lin Li. The welding variables recorded by QC appeared to comply with the WPS-B-T-2332-TC-P5-F.

FCAW welding process of weld joint 47 located on PCMK WSD1-FDSA4-4D/D. Welders are identified as 067184 ZPMC QC is identified as Mao Bin Bin. The welding variables recorded by QC appeared to comply with the WPS-B-T-2332-TC-P5-F.

FCAW welding process of weld joint 20 located on PCMK WSD1-FESA4-2C/C. Welders are identified as 068864 ZPMC QC is identified as Lin Li. The welding variables recorded by QC appeared to comply with the WPS-B-T-2332-TC-P5-F.

FCAW welding process of weld joint 48 located on PCMK WSD1-FDSA4-4D/D. Welders are identified as 068865 ZPMC QC is identified as Mao Bin Bin. The welding variables recorded by QC appeared to comply with the WPS-B-T-2332-TC-P5-F.

TRIAL ASSEMBLY YARD

This QA Inspector randomly observed the following work in progress.

OBG SEGMENT-3AW

SMAW welding process of weld joint005 located on PCMK SSD12-PP022. Welder is identified as 048617 ZPMC QC is identified as Zhang Qiang. The welding variables recorded by QC appeared to comply with the WPS-345-SMAW-2G (2F) Repair.

SMAW welding process of weld joint004 located on PCMK SSD10-PP020. Welder is identified as 054467 ZPMC QC is identified as Zhang Qiang. The welding variables recorded by QC appeared to comply with the WPS-345-SMAW-2G (2F) Repair.

Unless otherwise noted, all work observed on this dated appeared to generally comply with applicable contract documents.

Summary of Conversations:

No relevant conversation

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Serge Sinevod 13482570045, who represents the Office of Structural Materials for your project.

WELDING INSPECTION REPORT

(Continued Page 3 of 3)

Inspected By: Utekar,Shrikant

Quality Assurance Inspector

Reviewed By: Clifford,William

QA Reviewer